

## FastPort MIL-P3720 micro-code update.

Dear FastPort and PromICE user,

Sometimes when the manufacturer updates the code in the FastPort units, they inadvertently stop working with the PromICEs. The version of code included here in file '37fp0036.zip(containing 37fp0036.ihx)' works correctly with the PromICE.

The symptom of the new (non-working) code is that everything seems okay, but LoadICE software does not establish connection with the PromICE unit hooked to the FastPort.

Follow the manufacturer's documentation that came with the FastPort to set it up and give it an IP address etc. Then talk to it through a web browser and find the page where there is an item about upgrading the micro-code (firmware). Invoke that and when asked for, select the (previously unzipped 37fp0036.ihx file) and let the update happen.

Then proceed as usual with LoadICE etc. and everything should work.

We are providing this since several of the stock units in the past few months seem to have a version of code that does not work with the PromICE.

Sincerely,

PromICE Technical Support.

Arvind Rana

614-899-7754-x15

[support@gei.com](mailto:support@gei.com)

April 8<sup>th</sup> 2004